

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

91  
West  
1/8-1/4  
0.174 mi.  
917 ft.

**BLAST AUTO REPAIR + LUBE INC.**  
**2764 STILLWELL AVE**  
**BROOKLYN, NY 11224**

**NY AST A100293280**  
**N/A**

**Relative:**  
**Higher**

AST:

**Actual:**  
**1 ft.**

Name: BLAST AUTO REPAIR + LUBE INC.  
Address: 2764 STILLWELL AVE  
City,State,Zip: BROOKLYN, NY 11224  
Region: STATE  
DEC Region: 2  
Site Status: Active  
Facility Id: 2-609731  
  
Program Type: PBS  
UTM X: 586144.49289  
UTM Y: 4492628.11893  
Expiration Date: 10/18/2024  
Site Type: Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id: 332358  
Affiliation Type: Facility Owner  
Company Name: JOHN TRENT, INC.  
Contact Type: PRESIDENT  
Contact Name: AVNER FUZAYLOV  
Address1: 2775 STILLWELL AVE  
Address2: Not reported  
City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 449-0953  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KXLIU  
Date Last Modified: 2019-11-14

Site Id: 332358  
Affiliation Type: Mail Contact  
Company Name: BLAST AUTO REPAIR + LUBE INC  
Contact Type: Not reported  
Contact Name: AVNER FUZAYLUV  
Address1: 2764 STILLWELL AVE  
Address2: Not reported  
City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 449-0953  
EMail: BLASTAUTO@YAHOO.COM  
Fax Number: Not reported  
Modified By: CGFREEDM  
Date Last Modified: 2014-09-11

Site Id: 332358  
Affiliation Type: Facility Operator  
Company Name: BLAST AUTO REPAIR + LUBE INC.  
Contact Type: Not reported  
Contact Name: AVNER FUZAYLOV

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (718) 449-0953  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KXTANG  
Date Last Modified: 2004-10-18

Site Id: 332358  
Affiliation Type: Emergency Contact  
Company Name: AVNER FUZAYLOV  
Contact Type: Not reported  
Contact Name: AVNER FUZAYLOV  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (917) 721-6434  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KXTANG  
Date Last Modified: 2004-10-18

Tank Info:

Tank Number: 001  
Tank Id: 180460  
Material Code: 0022  
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None  
K00 - Spill Prevention - None  
E00 - Piping Secondary Containment - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
D00 - Pipe Type - No Piping  
L00 - Piping Leak Detection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.  
Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 09/12/2004  
Capacity Gallons: 275  
Tightness Test Method: NN  
Date Test: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: CGFREEDM  
Last Modified: 04/14/2017  
Material Name: waste oil/used oil

Tank Number: 002  
Tank Id: 180461  
Material Code: 0013  
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None  
K00 - Spill Prevention - None  
E00 - Piping Secondary Containment - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
D00 - Pipe Type - No Piping  
L00 - Piping Leak Detection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron

Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 09/12/2004  
Capacity Gallons: 275  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: CGFREEDM  
Last Modified: 04/14/2017  
Material Name: lube oil

Tank Number: 003  
Tank Id: 180462  
Material Code: 0013  
Common Name of Substance: Lube Oil

Equipment Records:

A00 - Tank Internal Protection - None  
K00 - Spill Prevention - None  
E00 - Piping Secondary Containment - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
D00 - Pipe Type - No Piping

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tank Location: L00 - Piping Leak Detection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.  
Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 09/12/2004  
Capacity Gallons: 275  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: CGFREEDM  
Last Modified: 04/14/2017  
Material Name: lube oil